

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:							
Company	Rusty Netz Environmental Coordinator	ī					
OGM	Karl Houskeeper Environmental Scientist III						

Inspection Report

Permit Number:	C0070035
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, July 17, 2007
Start Date/Time:	7/17/2007 12:00:00 PM
End Date/Time:	7/17/2007 3:30:00 PM
Last Inspection:	Tuesday, June 12, 2007

Inspector: Karl Houskeeper, Environmental Scientist II

Weather: Partly Cloudy, Temp. 85 Deg. F.

InspectionID Report Number: 1352

Accepted by: dhaddock

7/23/2007

Permitee: SUNNYSIDE COGENERATION ASSOCIATES Operator: SUNNYSIDE COGENERATION ASSOCIATES

Site: SUNNYSIDE REFUSE & SLURRY

Address: ONE POWER PLANT RD, PO BOX 159 SUNNYSIDE UT 84539

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Mineral Ownership Types of Operations

310.00	Total Permitted	☐ Federal		Underground
202.00	Total Disturbed	☐ State		Surface
	Phase I	☐ County		Loadout
	Phase II	✓ Fee		Processing
	Phase III	☐ Other	V	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

There are no pending compliance actions. The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. The permittee is complying with this stipulation.

Sediment ponds 007 and 012 have been cleaned. Sediment pond 009 is being cleaned and being expanded.

Inspector's Signature:

Salt. X Bushyse

Date

Wednesday, July 18, 2007

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

Permit Number: C0070035 Inspection Type: PARTIAL

Inspection Date: Tuesday, July 17, 2007

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	V		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		~	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations	Y		✓	
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		\checkmark	
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070035 Inspection Type: PARTIAL

Inspection Date: Tuesday, July 17, 2007

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

There are no pending compliance actions. The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. The permittee is complying with this stipulation.

2. Signs and Markers

The mine ID sign is located adjacent to the tipple on a light pole. The MSHA Refuse and Impoundment signs were also checked during the inspection and contained the required information.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Sediment ponds 007 and 012 have been cleaned. Sediment pond 009 (Pasture Pond) has being cleaned and expanded. Pond 009 now has the capacity to hold the additional drainage from the Slurry Cell 1&2, Clear Water Pond area. The Slurry Cell 1&2, Clear Water Pond site serves as an excess pile storage area.

4.e Hydrologic Balance: Effluent Limitations

Second Quarter 2007 water monitoring is in the EDI website, but has not been uploaded. Water monitoring is current.

7. Coal Mine Waste, Refuse Piles, Impoundments

Refuse pile is being mined in various lifts and areas depending on quality and plant demands. The refuse pile appeared stable with no visible hazards.